

## Under Review Notification

**Raised By:** VANESSA MOREL

**Product #:** DART TOOLING EUROCOPTER

**Date:** 18.1.24

**Product Name:** RBEM632V3009129

Part Number (D-Part and 9-Digit) (eg. D3535-11) (eg. D3535-25) (eg. D206-642-143)	Drawing or Document & <u>Current</u> Affected Revision for each part listed	"Y" or "N" Required for Each Part Do not leave blank							Reserved ECN Log Number	Instructions Relevant to Each Part (including whether CHG #'s will be affected)
		HOLD SHIPMENT	Red Tag/Quarantine Stock	Advise Customers	Stop Production	Re-Work Stock	IPP Under Review	Product Specifications Under Review ("Bluefiles")		
RBEM632V3009129-11	RBEM632V3009129 REV B	N	N	N	N	N	Y	Y	18-522	see below

**Description of Issue:** PRODUCTION / FIT ISSUE

Many issue has been detected with this design. Need a complete redesign. All drawings/parts/assembly that are in the RBEM632V3009129-11 HOLDER ASSY should be on hold for furthur build.

**Distribution:**

VP Operations Director of Operations Director Quality Assurance Director of Engineering	Chief Engineer Engineering Project Managers Engineering Clerk Customer Support Manager	Production Engineers Production Planners Purchasing Manager Technical Support	Product Manager - Solutions Provider
--	---	--	--------------------------------------